	Unitil / Fitchburg Gas & Electric Light Co.																	
	ELEVATED VOLTAGE REPORT																	
Report ID Re	eported By		Time of Event	Town	Street	Impacted Equipment	Equipment Owner (Utility/Municipality/Customer)	Weather Condition	Measured Elevated Voltage	Immediate Action	Repair Type		Date of Mitigation	Injury (yes/No	Asso.	Comments		
Pu	ıblic	1/10/2006	19:09	Fitchburg	Main Street	Street Light Pole	Unitil - FG&E	Clear	N/A	Permanent Repair	Cable - Repair	(1/10/2006	6 No		Conductor burnt @ base, energizing soil		
																		4
																		4
																		4
															-			4
													-	+	-			4
																		+
					-										+			+
Contac	ct Person:	Mark Frappier																
								-					-		1			
		+			-								+	+				+
					1			1						+				+
														1				†

Unitil / Fitchburg Gas & Electric Light Co. Manhole Event Tracking

Comments	ociated ident ID	ry (Y/N) Ass	Gas tected	e (if G	applicable)	Equipment	Failed Equipment Type	Cover Dislodged? (Y/N)*		Inspection	Manhole Number	Voltage Class	Feeder	Street	Town		Failure Date Failure	Cause	Customer Outage Hours	Number of Customers Interrupted	Manhole Report Type	Report ID
ner reported smoking manhole and flickering lights. ctor burnt @ submersed molimeter assembly causing	Cu Co ste	No	No	N	PILC	50 +	Cable	No	Solid	2/1/2006	88B	0 - 600v	NTWK	Oliver Street	Fitchburg	Rain	3/2/2007	Equipment Failure - Company	7.18	6	Smoking	F3072
					1																	
																				Mark Frappier	ontact Person:	Co
					1				1				-									
																				Mark Frappier	ontact Person:	Co

^{*}A "YES" response indicates that the manhole cover was either "AJAR" or "OFF CASTING"

Clear	Unitil - FG&E	Manhole Cover	Permanent Repair	Unitil - FG&E	Arrestor Replace/Repair	Yes		Manhole Explosion	Equipment Failure - Customer	Clear	0 - 600v	Solid	Yes	Cable	0 - 9	PILC	Yes	Yes
Temp below 32F	Customer Owned Equipment	Street Light Pole	Disconnected	Public	Cable - Repair	No		Smoking	Equipment Failure - Company	Temp below 32F	600v - 5kV	Slotted	No	Connector	19-Oct	EPR	No	No
Temp above 32F			None		Cable - Replace				Overload	Temp above 32F	5kv - 15kv			Splice	20 - 29	XLP		
Lightning					Neutral Repair				Improper installation	Lightning				Switch	30 - 39	600v	<u> </u>	
Nat. Disaster (Hurricane, flood, tornado, etc)					Customer Owned Equipment				Loose/Failed Connection	flood, tornado, etc)	,			Network Protector	30 - 49		<u> </u>	
Rain					Install Ground				Scheduled, Planned Work	Rain					50 +		<u> </u>	
Fog					Insulator Repair/Replace				Lightning Strike	Fog							<u> </u>	
Sleet/Ice					Luminares Change				Corrosion/Contamination/Decay	Sleet/Ice							<u> </u>	
Wind					None Required				Bird	Wind							<u> </u>	
Snow									Squirrel	Snow							<u> </u>	
Other, specify									Animal - Other	Other, specify							<u> </u>	
									Power Supply Interruption/Disturbance								<u> </u>	
									Operating Error/System Malfunction								<u> </u>	
									Action By Others								<u> </u>	
									Civil Emergency (Fire, etc)								<u> </u>	
									Human Contact									
									Vandalism								1	
									Vehicle Accident								1	
									Broken Limb/Tree								<u> </u>	
									Tree/Limb Contact - Growth into Lines									
									Patrolled Nothing Found									
									Other specify								1	